

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	12/14/2023	<b>Time:</b>	11:09 AM
<b>Name of School Corporation:</b>	ELKHART COMMUNITY SCHOOLS			<b>Corp ID:</b>	202305
<b>Address of School Corporation:</b>	2720 California Rd				
<b>City:</b>	Elkhart	<b>Zip:</b>	46514	<b>County Number:</b>	20
<b>VIN:</b>	1T7YT4A2X71289557	<b>License Number:</b>	30382	<b>Bus Number:</b>	107
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2006	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	D	<b>Mileage:</b>	147777	<b>Year:</b>	2007
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Wes Rowlander	<b>PE:</b>	7427

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-2	Any seat back or bottom is loose
24-1-1	The bus body has rust or rusted through areas which may weaken the body

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
46-2-3	Flip seat does not stay in the upright position when no passengers are seated

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**