

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Spot Checks	Date:	12/15/2023	Time:	10:23 AM		
Name of School Corporation:	UNION SCHOOL CORPORATION			Corp ID:	686795		
Address of School Corporation:	8707 W US 36						
City:	Modoc	Zip:	47358	County Number:	68		
VIN:	1GBJG31K591154524		License Number:	80600	Bus Number:	14	
Make of Body:	Collins Bus Corporation	Year:	2009	Make of Chassis:	Chevrolet	Year:	2009
Bus Type:	A2			Mileage:	111019		
Inspection Status:	R	Inspected By:	Steve Spallinger	PE:	6921		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
90-1-1	The trash container is not polyethylene or equivalent material
90-1-2	The trash container is greater than a fourteen (14) quart capacity
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
51-1-1	Any door seals are missing, damaged, or torn
17-1-1	Any dome light is inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.