## REPORT OF SCHOOL BUS INSPECTION

8:20 Type of Time: Annual Date: 1/23/2024 Inspection: AM Name of School Corporation: NORTH SPENCER COUNTY SCHOOL CO 747385 Corp ID: **Address of School Corporation:** 3720 E SR 162 County City: Lincoln City Zip: 47552 74 Number: License VIN: 1BAKJCBH2KF346829 21756 **Bus Number:** Number: Make of Blue Bird Blue Bird Year: 2017 Make of Body: Year: 2019 Corporation Chassis: Corporation **Bus Type:** Α1 Mileage: 40155 Inspection Inspected PE: R Philip Lubbers 7703 Status: By:

## **Violations - Rejected**

## <u>Inspection Code</u> <u>Description</u>

57-1-5 Step-well light is missing or inoperative

The seat belt cutter is not secured using a positive fastening method.

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.