

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 1/23/2024	<b>Time:</b> 10:22 AM
<b>Name of School Corporation:</b> NORTH SPENCER COUNTY SCHOOL CO	<b>Corp ID:</b> 747385	
<b>Address of School Corporation:</b> 3720 E SR 162		
<b>City:</b> Lincoln City	<b>Zip:</b> 47552	<b>County Number:</b> 74
<b>VIN:</b> 4DRBUSKP8EB417635	<b>License Number:</b> 7833	<b>Bus Number:</b> 17
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2012	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2014		
<b>Bus Type:</b> C	<b>Mileage:</b> 73956	
<b>Inspection Status:</b> R	<b>Inspected By:</b> Philip Lubbers	<b>PE:</b> 7703

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-5	There are any decals or stickers, except those required by law, in the windshield or in the windows to the immediate right or left of the driver
70-1-7	Any emergency window is too difficult to open

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.