

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 1/24/2024	<b>Time:</b> 10:24 AM	
<b>Name of School Corporation:</b> BARTHOLOMEW CONS. SCHOOL CORP.	<b>Corp ID:</b> 30365		
<b>Address of School Corporation:</b> 1260 N Marr Rd			
<b>City:</b> Columbus	<b>Zip:</b> 47201	<b>County Number:</b> 3	
<b>VIN:</b> 1HA6GUB70PN006221	<b>License Number:</b>	<b>Bus Number:</b> W14	
<b>Make of Body:</b> Endera	<b>Year:</b> 2023	<b>Make of Chassis:</b> Chevrolet	<b>Year:</b> 2023
<b>Bus Type:</b>	<b>Mileage:</b> 12956		
<b>Inspection Status:</b> A	<b>Inspected By:</b> Seth Davidson	<b>PE:</b> 8101	

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

Bus Type Description