

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/29/2024	Time:	11:23 AM
Name of School Corporation:	MISSISSINEWA COMM. SCHOOL CORP	Corp ID:	272855		
Address of School Corporation:	424 E South A St				
City:	Gas City	Zip:	46933	County Number:	27
VIN:	4UZABRFCXRCUK4622	License Number:	26346	Bus Number:	8
Make of Body:	Thomas Built Buses, Inc.	Year:	2023	Make of Chassis:	Freightliner
Bus Type:	C	Mileage:	6776	Year:	2024
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-1	Any headlight is inoperative
55-1-3	Power steering is inoperative
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
33-1-1	The grill has any exposed edges that may cause injury

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.