REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	1/29/2024	**Time:**	10:38 AM
Name of School Corporation:	PRIMROSE SCHOOL OF W. FISHERS			**Corp ID:**	290004
Address of School Corporation:	12609 Parkside Dr.				
City:	Fishers	**Zip:**	46038	**County Number:**	29
VIN:	1GBHG31C081109884	**License Number:**	B733D	**Bus Number:**	1
Make of Body:	Chevrolet **Year:** 2008	**Make of Chassis:**	Chevrolet	**Year:**	2008
Bus Type:	A1	**Mileage:**	86240		
Inspection Status:	O	**Inspected By:**	Jeff Stone	**PE:**	8184

Violations - Rejected

Inspection Code	Description
48-1-1	Power steering unit leaks at any point

Violations - Out of Service

Inspection Code	Description
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)
10-2-2	The parking brake fails to hold the bus during the testing procedure. (Note – It is NOT a violation if the test cannot be done due to OEM design

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**