

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------|------------------------|-------------|-------------------------|----------------|
| Type of Inspection: | Re-Inspection | Date: | 1/31/2024 | Time: | 11:13 AM |
| Name of School Corporation: | M.S.D. LAWRENCE TOWNSHIP | Corp ID: | 495330 | | |
| Address of School Corporation: | 5850 Thunderbird Rd | | | | |
| City: | Indianapolis | Zip: | 46236 | County Number: | 49 |
| VIN: | 4DRBWAAR8CB591385 | License Number: | 1420 | Bus Number: | 18 |
| Make of Body: | IC Corporation | Year: | 2012 | Make of Chassis: | IC Corporation |
| Year: | 2012 | Year: | 2012 | | |
| Bus Type: | D | Mileage: | 135071 | | |
| Inspection Status: | O | Inspected By: | Joel Flores | PE: | 7415 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 70-1-10 | If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 59-2-3 | Stop arm does not fully extend to a right angle to the bus |
| 70-2-3 | Any emergency window will not open |

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.