

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 2/1/2024	<b>Time:</b> 2:04 PM
<b>Name of School Corporation:</b> BORDEN-HENRYVILLE SCHOOL CORP	<b>Corp ID:</b> 0935	
<b>Address of School Corporation:</b> 207 E. Main St.		
<b>City:</b> Borden	<b>Zip:</b> 47106	<b>County Number:</b> 10
<b>VIN:</b> 4DRBUSKN2EB417581	<b>License Number:</b> 6843	<b>Bus Number:</b> 418
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2014	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2014	<b>Mileage:</b> 103842	<b>PE:</b> 5171
<b>Bus Type:</b> C	<b>Inspected By:</b> Troy Boyd	
<b>Inspection Status:</b> O		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**