## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual Date: 2/8/2024 Time: 9:21 AM

Name of School Corporation: SUNMAN-DEARBORN COMM. SCH CORP Corp ID: 151560

**Address of School Corporation:** 1 Trojan Place STE B

City: St Leon Zip: 47012 **County Number:** 15 VIN: 4DRBVAAR28A495056 **Bus Number:** License Number: B427F 33A 2008 Make of Body: IC Corporation Year: 2006 Make of Chassis: IC Corporation Year:

**Bus Type:** D Mileage: 97662

PE: Inspection Status: O Inspected By: Chris Clark 6665

## **Violations - Rejected**

**Description Inspection Code** 

64-1-4 Any front turn signal does not function properly

## **Violations - Out of Service**

<u>Inspection</u> <u>Code</u>	<u>Description</u>
64-2-1	Any rear turn signal does not function properly
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
65-2-1	Warning lights fail to operate correctly

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.