REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | Date: | 2/13/2024 | Time: | 9:48 AM |
|---------------------------------|--|---------------------------|------------------------|-----------------------------|-------------------|------------|
| Name of Schoo Address of Sch | I Corporation: SO | JTH SPENCE 321 South 5 | R CO. SCHOOL 5th St | CORP. | Corp ID: | 747445 |
| City: | Rockport | Zip: | 47635 | | County Number: | 74 |
| VIN: | 4UZABRDU7ECFK8770 | | License Number: | 6066 | Bus Number: | 21 |
| Make of Body: | Thomas Built Buses, Yea Inc. | r: 2013 | Make of Chassis: | Thomas Built Buses, Inc. | Year: | 2014 |
| Bus Type: | С | | Mileage: | 73095 | | |
| Inspection Status: | R | Inspected By: | Philip Lubbers | | PE: | 7703 |

Violations - Rejected

| Inspection Code | Description |
|-----------------|--|
| 46-1-5 | Upholstery or padding is ripped, torn, or improperly repaired |
| 50-1-2 | The seat belt cutter is not secured using a positive fastening method. |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.