REPORT OF SCHOOL BUS INSPECTION

Type of 1:57 Time: Post-Crash Inspection Date: 2/13/2024 Inspection: PM Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300 **Address of School Corporation:** 5808 E Administration Rd County City: Marengo Zip: 47140 13 Number: License VIN: 1BAKJCPA3BF278651 B531U Bus Number: 33A Number: Make of Blue Bird Blue Bird Year: 2010 Make of Body: Year: 2011 Corporation Chassis: Corporation **Bus Type:** С Mileage: Unknown Inspection Inspected 0 PE: Philip Lubbers 7703 Status: By:

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

41-1-4 There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

Inspection Code Description

70-2-1 Any glass or glazing is broken through or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.