

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/13/2024	Time:	1:34 PM		
Name of School Corporation:	GREATER CLARK CO SCHLS			Corp ID:	101010		
Address of School Corporation:	301 E 11th St						
City:	Jeffersonville	Zip:	47130	County Number:	10		
VIN:	4DRBUC8P9GB724232		License Number:	10061	Bus Number:	162	
Make of Body:	IC Corporation	Year:	2016	Make of Chassis:	IC Corporation	Year:	2016
Bus Type:	C			Mileage:	100292		
Inspection Status:	O	Inspected By:	Troy Boyd	PE:	5171		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
55-1-3	Power steering is inoperative
55-1-2	There is movement at any spring loaded drag link or the rod end (using hand pressure)
19-1-8	See Notes: Any defect inspector deems a violation not listed
59-1-10	A stop arm camera installed so as to not allow the capture of the image of the stop arm extended with red lights flashing, image of the rear license plate of passing vehicle, and include up to 2 lanes of traffic to left or right or both sides of the bus
58-1-1	Any stirrup step or handle is broken, loose or missing
15-1-1	The defroster system is not working properly.
68-1-3	Reservoir is empty
68-1-1	Washers do not function properly in any manner
53-1-2	Any leaf spring extends more than 1/4 inch beyond the vertical alignment of the spring stack
53-1-3	Any spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
31-1-3	See Notes: Any defect inspector deems a violation not listed
4-1-2	See Notes: Any defect inspector deems a violation not listed
52-1-1	There are any loose, broken, or missing mountings
70-1-12	See Notes: Any defect inspector deems a violation not listed
70-1-4	There is any cracked glass to the immediate right or left of the driver
3-1-7	Battery compartment door is not securely fastened.
51-1-4	See Notes: Any defect inspector deems a violation not listed
17-1-1	Any dome light is inoperative
33-1-4	See Notes: Any defect inspector deems a violation not listed
33-1-2	The grill is missing
33-1-1	The grill has any exposed edges that may cause injury
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
46-1-4	There are any sharp edges or protrusions
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
40-1-1	Any required instrument or gauge is missing. (Speedometer, Odometer, Fuel Gauge, High beam, Brake indicator light or gauge, air pressure gauge, brake warning light, DEF Gauge)
11-1-7	See Notes: Any defect inspector deems a violation not listed
34-1-1	Any headlight is inoperative

64-1-4 Any front turn signal does not function properly
 69-1-1 Wiper motors are not of sufficient power to operate the wiper blades
 44-1-1 Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat
59-2-4	Stop arm does not function properly
59-2-3	Stop arm does not fully extend to a right angle to the bus
34-2-2	Both lamps are inoperative on high beam
34-2-1	Both lamps are inoperative on low beam
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
39-2-1	Inner fenders are loose from body or mounting brackets
69-2-1	Wipers fail to function
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
24-2-2	Any body surface protrudes beyond the normal limits of the body structure

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.