

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	2/14/2024	Time:	11:00 AM
Name of School Corporation:	NORTH MONTGOMERY COMM SCH CORP			Corp ID:	545835
Address of School Corporation:	480 W 580 N				
City:	Crawfordsville	Zip:	47933	County Number:	54
VIN:	4DRBUC8N3HB373379			License Number:	10914
Make of Body:	IC Corporation	Year:	2015	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	81402	Year:	2017
Inspection Status:	R	Inspected By:	Nate King	PE:	7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-1	The front bumper does not extend to the edge of the fenders
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals
33-1-1	The grill has any exposed edges that may cause injury

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.