

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|------------------------|-----------|-------------------------|----------------|
| Type of Inspection: | Annual | Date: | 2/14/2024 | Time: | 11:00 AM |
| Name of School Corporation: | NORTH MONTGOMERY COMM SCH CORP | | | Corp ID: | 545835 |
| Address of School Corporation: | 480 W 580 N | | | | |
| City: | Crawfordsville | Zip: | 47933 | County Number: | 54 |
| VIN: | 4DRBUC8N3HB373379 | License Number: | 10914 | Bus Number: | 22 |
| Make of Body: | IC Corporation | Year: | 2015 | Make of Chassis: | IC Corporation |
| Year: | 2015 | Year: | 2017 | Year: | 2017 |
| Bus Type: | C | Mileage: | 81402 | PE: | 7421 |
| Inspection Status: | R | Inspected By: | Nate King | PE: | 7421 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 11-1-1 | The front bumper does not extend to the edge of the fenders |
| 11-1-2 | The front or rear bumper is not properly attached, missing, torn, loose, or altered. |
| 24-1-2 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |
| 16-1-1 | There are any leaks from the differential, pinion seal, hubs or wheel seals |
| 33-1-1 | The grill has any exposed edges that may cause injury |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.