

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/15/2024	Time:	11:38 AM
Name of School Corporation:	MITCHELL COMMUNITY SCHOOLS	Corp ID:	475085		
Address of School Corporation:	441 N 8th St				
City:	Mitchell	Zip:	46446	County Number:	47
VIN:	1GBJG31K491112586	License Number:	79559	Bus Number:	SP1
Make of Body:	Collins Bus Corporation	Year:	2009	Make of Chassis:	Chevrolet
Bus Type:		Mileage:	59185	Year:	2009
Inspection Status:	O	Inspected By:	Seth Davidson	PE:	8101

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
19-1-8	See Notes: Any defect inspector deems a violation not listed
41-1-1	There are objects blocking aisles or exits
41-1-9	See Notes: Any defect inspector deems a violation not listed
41-1-2	Any interior protrusions have sharp edges or corners
20-1-10	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-1	Any glass or glazing is broken through or missing
19-2-2	Seat is not securely attached to the floor and does not have at least four (4) inch fore-and- aft adjustment
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
20-2-2	Door glass is missing
46-2-2	Any seat is broken or not attached to the floor

Bus Type Description