

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection	Date: 2/15/2024	Time: 3:38 PM
Name of School Corporation: MITCHELL COMMUNITY SCHOOLS	Corp ID: 475085	
Address of School Corporation: 441 N 8th St		
City: Mitchell	Zip: 46446	County Number: 47
VIN: 1GBJG31K491112586	License Number: 79559	Bus Number: SP1
Make of Body: Collins Bus Corporation	Year: 2009	Make of Chassis: Chevrolet
Year: 2009	Mileage: 59758	Year: 2009
Bus Type:		
Inspection Status: O	Inspected By: Seth Davidson	PE: 8101

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-9	See Notes: Any defect inspector deems a violation not listed
41-1-1	There are objects blocking aisles or exits
41-1-2	Any interior protrusions have sharp edges or corners
19-1-8	See Notes: Any defect inspector deems a violation not listed
20-1-10	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed
46-2-2	Any seat is broken or not attached to the floor
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
19-2-2	Seat is not securely attached to the floor and does not have at least four (4) inch fore-and- aft adjustment
20-2-2	Door glass is missing
70-2-1	Any glass or glazing is broken through or missing

Bus Type Description