REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:2/20/2024 Time:10:35 AMName of School Corporation: PAOLI COMMUNITY SCHOOL CORP.Corp ID:596155

Address of School Corporation: 501 S Elm St

City:PaoliZip:47454County Number: 59VIN:1GB3GSBGOG1138211License Number: 60889Bus Number: A6Make of Body:Chevrolet Year: 2016Make of Chassis: Chevrolet Year: 2016

Bus Type: A2 Mileage: 57868

Inspection Status: O Inspected By: Philip Lubbers PE: 7703

Violations - Rejected

Inspection Code	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

<u>Inspection</u> <u>Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the
	bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.