

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 2/20/2024 **Time:** 10:35 AM
Name of School Corporation: PAOLI COMMUNITY SCHOOL CORP. **Corp ID:** 596155
Address of School Corporation: 501 S Elm St
City: Paoli **Zip:** 47454 **County Number:** 59
VIN: 1GB3GSBGOG1138211 **License Number:** 60889 **Bus Number:** A6
Make of Body: Chevrolet **Year:** 2016 **Make of Chassis:** Chevrolet **Year:** 2016
Bus Type: A2 **Mileage:** 57868
Inspection Status: O **Inspected By:** Philip Lubbers **PE:** 7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.