REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	2/21/2024	**Time:**	8:51 AM
Name of School Corporation:	PAOLI COMMUNITY SCHOOL CORP.				**Corp ID:**	596155
Address of School Corporation:	501 S Elm St					
City:	Paoli	**Zip:**	47454		**County Number:**	59
VIN:	4DRBUC8P7JB421974		**License Number:**	72233	**Bus Number:**	P22
Make of Body:	IC Corporation	**Year:** 2017	**Make of Chassis:**	IC Corporation	**Year:**	2018
Bus Type:	C		**Mileage:**	48579		
Inspection Status:	O	**Inspected By:**	Philip Lubbers		**PE:**	7703

Violations - Rejected

Inspection Code	Description
57-1-5	Step-well light is missing or inoperative
63-1-3	Any front tire has less than 4/32 inch tread depth when measured in any two adjacent major grooves
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.