

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 2/21/2024	Time: 8:51 AM	
Name of School Corporation: PAOLI COMMUNITY SCHOOL CORP.	Corp ID: 596155		
Address of School Corporation: 501 S Elm St			
City: Paoli	Zip: 47454	County Number: 59	
VIN: 4DRBUC8P7JB421974	License Number: 72233	Bus Number: P22	
Make of Body: IC Corporation	Year: 2017	Make of Chassis: IC Corporation	Year: 2018
Bus Type: C	Mileage: 48579		
Inspection Status: O	Inspected By: Philip Lubbers	PE: 7703	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative
63-1-3	Any front tire has less than 4/32 inch tread depth when measured in any two adjacent major grooves
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.