

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	2/22/2024	Time:	10:05 AM
Name of School Corporation:	FIRST STUDENT - INDPLS			Corp ID:	4981
Address of School Corporation:	xxx				
City:	Indianapolis	Zip:	46202	County Number:	49
VIN:	4UZABRFC2MCMN7557	License Number:	B900R	Bus Number:	809
Make of Body:	Thomas Built Buses, Inc.	Year:	2020	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C			Mileage:	655578
Inspection Status:	O	Inspected By:	Joel Flores	PE:	7415

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
46-1-10	See Notes: Any defect inspector deems a violation not listed
95-1-15	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
11-2-2	A bumper does not meet manufactures specifications

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.