

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 2/26/2024 **Time:** 10:34 AM
Name of School Corporation: RICHLAND-BEAN BLOSSOM C.S.CORP **Corp ID:** 535705
Address of School Corporation: 600 S Edgewood Dr
City: Ellettsville **Zip:** 47429 **County Number:** 53
VIN: 4DRBUC8P7KB335050 **License Number:** B236V **Bus Number:** 17
Make of Body: IC Corporation **Year:** 2017 **Make of Chassis:** IC Corporation **Year:** 2019
Bus Type: C **Mileage:** 44273
Inspection Status: R **Inspected By:** Mike Adams **PE:** 7407

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-2	A lens is cracked, missing or wrong color
64-1-4	Any front turn signal does not function properly

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.