

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual **Date:** 2/27/2024 **Time:** 8:53 AM  
**Name of School Corporation:** PERRY CENTRAL COMM. SCH. CORP. **Corp ID:** 626325  
**Address of School Corporation:** 18677 Old State Rd 37  
**City:** Leopold **Zip:** 47551 **County Number:** 62  
**VIN:** 1GB3GSBG4G1187573 **License Number:** 90381 **Bus Number:** 603  
**Make of Body:** Chevrolet **Year:** 2015 **Make of Chassis:** Chevrolet **Year:** 2016  
**Bus Type:** **Mileage:** 42072  
**Inspection Status:** O **Inspected By:** Philip Lubbers **PE:** 7703

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------