REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	2/27/2024	**Time:**	8:53 AM
Name of School Corporation:	PERRY CENTRAL COMM. SCH. CORP.			**Corp ID:**	626325
Address of School Corporation:	18677 Old State Rd 37				
City:	Leopold	**Zip:**	47551	**County Number:**	62
VIN:	1GB3GSBG4G1187573	**License Number:**	90381	**Bus Number:**	603
Make of Body:	Chevrolet **Year:** 2015	**Make of Chassis:**	Chevrolet	**Year:**	2016
Bus Type:		**Mileage:**	42072		
Inspection Status:	O	**Inspected By:**	Philip Lubbers	**PE:**	7703

Violations - Rejected

Inspection Code	Description
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)

Violations - Out of Service

Inspection Code	Description

Bus Type Description