## REPORT OF SCHOOL BUS INSPECTION

Type of 9:01 Annual Time: Date: 3/5/2024 Inspection: AM Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL Corp ID: 141375 **Address of School Corporation:** 5494 E SR 58 County City: Elnora Zip: 47529 14 Number: License VIN: 1BAKFCKH45F229145 B668B Bus Number: Number: Make of Blue Bird Blue Bird Make of Body: Year: 2004 Year: 2005 Corporation Chassis: Corporation **Bus Type:** С Mileage: 151434 Inspection Inspected О PE: 7703 Philip Lubbers Status: By:

## Violations - Rejected

<u>Inspection</u> <u>Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.