

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 3/5/2024	Time: 9:13 AM
Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL	Corp ID: 141375	
Address of School Corporation: 5494 E SR 58		
City: Elnora	Zip: 47529	County Number: 14
VIN: 4DRBUC8P8GB138606	License Number: 25600	Bus Number: ND6
Make of Body: IC Corporation	Year: 2015	Make of Chassis: IC Corporation
Bus Type: A1	Mileage: 47276	Year: 2016
Inspection Status: R	Inspected By: Philip Lubbers	PE: 7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.