

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/5/2024	Time:	10:01 AM		
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			Corp ID:	141375		
Address of School Corporation:	5494 E SR 58						
City:	Elnora	Zip:	47529	County Number:	14		
VIN:	4DRBUC8P4GB734618		License Number:	9535	Bus Number:	ND7	
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation	Year:	2016
Bus Type:	C			Mileage:	68289		
Inspection Status:	R	Inspected By:	Philip Lubbers	PE:	7703		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
17-1-1	Any dome light is inoperative
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.