REPORT OF SCHOOL BUS INSPECTION

Type of 8:51 Time: Annual Date: 3/6/2024 Inspection: AM NORTH DAVIESS CO. COMM. SCHOOL Name of School Corporation: Corp ID: 141375 **Address of School Corporation:** 5494 E SR 58 County City: Elnora Zip: 47529 14 Number: License VIN: 4UZABRDJ9ACAN3249 B620Q Bus Number: 13 Number: Thomas Built Buses, Year: 2009 Thomas Built Buses, Year: Make of Make of Body: 2010 Chassis: Inc. **Bus Type:** С Mileage: 164997 Inspection Inspected R Philip Lubbers PE: 7703 Status: By:

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.