

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 3/8/2024	Time: 9:17 AM
Name of School Corporation: NORTH LAWRENCE COMM. SCHOOLS	Corp ID: 475075	
Address of School Corporation: 595 Stars Blvd		
City: Bedford	Zip: 47421	County Number: 47
VIN: 4DRBUAAN95B978727	License Number: 20437	Bus Number: A33
Make of Body: IC Corporation	Year: 2004	Make of Chassis: IC Corporation
Year: 2005		
Bus Type: C	Mileage: 157663	
Inspection Status: O	Inspected By: Seth Davidson	PE: 8101

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
16-2-1	When any wheel seal is leaking and includes evidence of wet contaminated brake friction material and accompanied by evidence that further leaking will occur.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.