

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual      **Date:** 3/11/2024      **Time:** 8:55 AM  
**Name of School Corporation:** NORTH LAWRENCE COMM. SCHOOLS      **Corp ID:** 475075  
**Address of School Corporation:** 595 Stars Blvd  
**City:** Bedford      **Zip:** 47421      **County Number:** 47  
**VIN:** 1GB3GSBG3L1259177      **License Number:** 91515      **Bus Number:** V43  
**Make of Body:** Chevrolet      **Year:** 2020      **Make of Chassis:** Chevrolet      **Year:** 2020  
**Bus Type:**      **Mileage:** 25039  
**Inspection Status:** A      **Inspected By:** Seth Davidson      **PE:** 8101

### Violations - Rejected

### Inspection Code Description

### Violations - Out of Service

### Inspection Code Description

### Bus Type Description