

# REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual      **Date:** 3/11/2024      **Time:** 9:01 AM  
**Name of School Corporation:** NORTH LAWRENCE COMM. SCHOOLS      **Corp ID:** 475075  
**Address of School Corporation:** 595 Stars Blvd  
**City:** Bedford      **Zip:** 47421      **County Number:** 47  
**VIN:** 1GB3GSBG6L1259187      **License Number:** 93223      **Bus Number:** V44  
**Make of Body:** Chevrolet      **Year:** 2020      **Make of Chassis:** Chevrolet      **Year:** 2020  
**Bus Type:**      **Mileage:** 20108  
**Inspection Status:** A      **Inspected By:** Seth Davidson      **PE:** 8101

## Violations - Rejected

## Inspection Code Description

## Violations - Out of Service

## Inspection Code Description

## Bus Type Description