REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | Date: | 3/11/2024 | Time: | 11:26 AM |
|---------------------------------|--|-------------------------|---------------------|-----------------------------|-------------------|-------------|
| Name of Schoo Address of Sch | I Corporation: JAY ool Corporation: | SCHOOL CC PO Box 123 | RPORATION 39 | | Corp ID: | 383945 |
| City: | Portland | Zip: | 47371 | | County Number: | 38 |
| VIN: | 4UZABRFC0RCUJ6335 | | License Number: | 26366 | Bus Number: | 42 |
| Make of Body: | Thomas Built Buses, Yea Inc. | r: 2023 | Make of Chassis: | Thomas Built Buses, Inc. | Year: | 2023 |
| Bus Type: | С | | Mileage: | 9817 | | |
| Inspection Status: | 0 | Inspected By: | Steve Spalling | er | PE: | 6921 |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection
CodeDescription7-2-4Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at
other than a proper connection).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.