

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                          |                        |                |                         |              |
|---------------------------------------|--------------------------|------------------------|----------------|-------------------------|--------------|
| <b>Type of Inspection:</b>            | Re-Inspection            | <b>Date:</b>           | 3/13/2024      | <b>Time:</b>            | 10:42 AM     |
| <b>Name of School Corporation:</b>    | BROWN"S BUS TRANSPORTION |                        |                | <b>Corp ID:</b>         | 82008Z       |
| <b>Address of School Corporation:</b> | 2120 Culverson           |                        |                |                         |              |
| <b>City:</b>                          | Evansville               | <b>Zip:</b>            | 47714          | <b>County Number:</b>   | 82           |
| <b>VIN:</b>                           | 4UZAAXAL93CK75366        | <b>License Number:</b> | B449L          | <b>Bus Number:</b>      | M8           |
| <b>Make of Body:</b>                  | Freightliner             | <b>Year:</b>           | 2002           | <b>Make of Chassis:</b> | Freightliner |
| <b>Bus Type:</b>                      | C                        | <b>Mileage:</b>        | 144528         | <b>Year:</b>            | 2003         |
| <b>Inspection Status:</b>             | O                        | <b>Inspected By:</b>   | Bradley Miller | <b>PE:</b>              | 7809         |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                                                                                           |
|------------------------|--------------------------------------------------------------------------------------------------------------|
| 44-1-1                 | Any marker light or lens is missing, cracked, faded, wrong color, or inoperative                             |
| 70-1-10                | If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle |
| 68-1-1                 | Washers do not function properly in any manner                                                               |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.