

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 3/14/2024	Time: 9:19 AM
Name of School Corporation: PERU COMMUNITY SCHOOLS	Corp ID: 525635	
Address of School Corporation: 35 W 3rd St		
City: Peru	Zip: 46970	County Number: 52
VIN: 1GB6G2AG7A1167176	License Number: 84000	Bus Number: Tiger1
Make of Body: Starcraft	Year: 2009	Make of Chassis: Chevrolet
		Year: 2010
Bus Type: A2	Mileage: 122250	
Inspection Status: R	Inspected By: Randy McPike	PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-7	Non safety related signs/decorations posted.
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.