

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/14/2024	Time:	10:13 AM		
Name of School Corporation:	PERU COMMUNITY SCHOOLS			Corp ID:	525635		
Address of School Corporation: 35 W 3rd St							
City:	Peru	Zip:	46970	County Number:	52		
VIN:	1GB6G3AGXA1168294		License Number:	83999	Bus Number:	Tiger2	
Make of Body:	Starcraft	Year:	2010	Make of Chassis:	Chevrolet	Year:	2010
Bus Type:	A2			Mileage:	142027		
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.