REPORT OF SCHOOL BUS INSPECTION

Type of 10:28 3/14/2024 Time: Annual Date: Inspection: AM Name of School Corporation: PERU COMMUNITY SCHOOLS Corp ID: 525635 **Address of School Corporation:** 35 W 3rd St County City: Peru Zip: 46970 52 Number: License VIN: 4UZABRDJ59CAD3295 32092 **Bus Number:** 11 Number: Make of Thomas Built Buses, Year: 2008 Freightliner Year: 2009 Make of Body: Inc. Chassis: **Bus Type:** C Mileage: 163585 Inspection Inspected R PE: 7018 Randy McPike Status: By:

Description

Violations - Rejected

Inspection Code

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

29-1-2 Floor covering is missing, cut, loose, buckled, bulging, or not secure

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.