REPORT OF SCHOOL BUS INSPECTION

Type of 9:55 Annual Date: 3/15/2024 **Time**: Inspection: AM Name of School Corporation: PERU COMMUNITY SCHOOLS Corp ID: 525635 Address of School Corporation: 35 W 3rd St County City: Peru Zip: 46970 52 Number: License VIN: 14283 4UZABRDTXHCHP8452 **Bus Number:** 24 Number: Make of Thomas Built Buses, Make of Body: Year: 2015 Freightliner Year: 2017 Inc. Chassis: **Bus Type:** С Mileage: 161231 Inspected PE: 7018 **Inspection Status:** R Randy McPike By:

Violations - Rejected

Inspection Code	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.