REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection 3/15/2024 **Time**: Date: 10:00 AM

Name of School Corporation: PERU COMMUNITY SCHOOLS

Corp ID: 525635

Address of School Corporation: 35 W 3rd St

City: Peru Zip: 46970 **County Number: 52** VIN: 4UZABRFC7RCUD2446 **Bus Number:** 7 License Number: 25966 Make of Body: Make of Chassis: Freightliner Year: 2024 Freightliner Year: 2022 Mileage: 28315

Bus Type: С

Inspection Status: A Inspected By: Randy McPike PE: 7018

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.