REPORT OF SCHOOL BUS INSPECTION

9:23 Type of Time: Annual Date: 3/18/2024 Inspection: AM NORTHEAST DUBOIS CO. SCH. CORP 192040 Name of School Corporation: Corp ID: **Address of School Corporation:** 5379 E Main St County City: **Dubois** Zip: 47527 19 Number: License VIN: 1BAKFCKH95F227326 B512K Bus Number: 2 Number: Make of Blue Bird Blue Bird Make of Body: Year: 2004 Year: 2005 Corporation Chassis: Corporation Bus Type: D Mileage: 220499 Inspection Inspected PE: R Philip Lubbers 7703 Status: By:

Violations - Rejected

Inspection Ocode Description

Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.