

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 3/21/2024	<b>Time:</b> 9:54 AM
<b>Name of School Corporation:</b> HOLY TRINITY CATHOLIC SCHOOL	<b>Corp ID:</b> 19A865	
<b>Address of School Corporation:</b> 990 Church Ave		
<b>City:</b> Jasper	<b>Zip:</b> 47546	<b>County Number:</b> 19
<b>VIN:</b> 1BABKCPA68F250641	<b>License Number:</b> B870K	<b>Bus Number:</b> 3
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2007	<b>Make of Chassis:</b> Freightliner
<b>Year:</b> 2008	<b>Mileage:</b> 102286	
<b>Bus Type:</b> C		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Philip Lubbers	<b>PE:</b> 7703

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
68-1-1	Washers do not function properly in any manner
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**