## REPORT OF SCHOOL BUS INSPECTION

Type of Annual Date: 3/22/2024 Time: 10:51 AM

Name of School Corporation: BLACKFORD COUNTY SCHOOLS Corp ID: 50515

**Address of School Corporation:** 668 W CR 200S

City:Hartford CityZip:47348County Number:5VIN:4DRBUC8N5KB291726License Number:22499Bus Number:118

Make of Body: IC Corporation Year: 2018 Make of Chassis: IC Corporation Year: 2019

Bus Type: C Mileage: 87968

Inspection Status: R Inspected By: Steve Spallinger PE: 6921

## **Violations - Rejected**

## <u>Inspection Code</u> <u>Description</u>

23-1-5 Any hanger, clamp or bracket is missing, loose or broken

46-1-1 Any seat is loose from the floor or seat rail

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.