REPORT OF SCHOOL BUS INSPECTION

3/26/2024 Time: 9:44 AM **Type of Inspection:** Annual Date: Corp ID: 454615

LAKE CENTRAL SCHOOL CORP. Name of School Corporation:

Address of School Corporation: City: St John Zip: 46373 **County Number: 45** VIN: 4DRBUC8N4JB709983 **Bus Number:** License Number: 19467 Make of Body: IC Corporation Year: 2017 Make of Chassis: IC Corporation Year: 2018

8855 Wicker Ave

Bus Type: С Mileage: 97430

PE: **Inspection Status:** R **Inspected By:** Tim Grayson 7558

Violations - Rejected

Description **Inspection Code**

41-1-4 There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.