REPORT OF SCHOOL BUS INSPECTION

Type of Re-Inspection Date: 3/28/2024 Time: 10:19 AM

Name of School
Corporation:

PRIMROSE SCHOOL OF NOBLESVILLE
Corp ID: 290008

Address of School Corporation: 15707 North Point Blvd.

City: Noblesville Zip: 46060 County Number: 29

VIN: 1GB0GRBF5H1105922 License Number: 4

Make of Body:Chevrolet Year: 2017Make of Collins Bus CorporationCollins Bus CorporationYear: 2017

Bus Type: Mileage: 20052

Inspection Status: O Inspected By: Nick Cox PE: 8795

Violations - Rejected

Inspection Code Description

70-1-9 If the words "EMERGENCY EXIT" does not appear on the top or bottom of the window

or directly above each emergency exit window on the inside of the bus

41-1-4 There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

Inspection Code Description

Bus Type Description