## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection: Annual			Date:	4/1/2024	Time:	8:52 AM
Name of School Corporation:		OMO SCHOOL	CORPORATION		Corp ID:	343500
Address of School	Corporation:	620 W Deffenb	augh			
City:	Kokomo	Zip:	46901		County Number:	34
VIN:	4DRBWAAR4FB143	424	License Number:	7186	Bus Number:	221
Make of Body:	IC Corporation Year:	2014	Make of Chassis:	IC Corporation	Year:	2015
Bus Type:	D		Mileage:	102821		
Inspection Status:	0	Inspected By:	Randy McPike		PE:	7018

**Violations - Rejected** 

Inspection Code	Description
46-1-2	Any seat back or bottom is loose

## Violations - Out of Service

Inspection <u>Code</u>	Description
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
65-2-1	Warning lights fail to operate correctly
46-2-3	Flip seat does not stay in the upright position when no passengers are seated

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.