## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:4/2/2024Time:9:32 AMName of School Corporation:RSI TRUCK & BUS REPAIR, INCCorp ID:45005Z

Address of School Corporation: 3333 Sheffield Ave

City:HammondZip:46327County Number:45VIN:4DRBUAAN3CB591345License Number:Bus Number:5Make of Body:IC Corporation Year:2012

Bus Type: C Mileage: 134692

Inspection Status: R Inspected By: Tim Grayson PE: 7558

## Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

23-1-5 Any hanger, clamp or bracket is missing, loose or broken

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.