

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual      **Date:** 4/2/2024      **Time:** 10:12 AM  
**Name of School Corporation:** KOKOMO SCHOOL CORPORATION      **Corp ID:** 343500  
**Address of School Corporation:** 620 W Deffenbaugh  
**City:** Kokomo      **Zip:** 46901      **County Number:** 34  
**VIN:** 1GB3GRBG9H1342127      **License Number:** 56866      **Bus Number:** 107  
**Make of Body:** Starcraft      **Year:** 2017      **Make of Chassis:** Chevrolet      **Year:** 2018  
**Bus Type:** A2      **Mileage:** 32436  
**Inspection Status:** O      **Inspected By:** Randy McPike      **PE:** 7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.