REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:4/10/2024 Time:8:01 AM

Name of School Corporation: HANOVER COMM. SCHOOL CORP. Corp ID: 454580

Address of School Corporation: PO Box 645

City:Cedar LakeZip:46303County Number: 45VIN:1GB3G2BG1C1196659License Number: 14188Bus Number: 44Make of Body:Star Trans Year: 2012Make of Chassis: Chevrolet Year: 2012

Bus Type: Mileage: 85992

Inspection Status: A Inspected By: Tim Grayson PE: 7558

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description