

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 4/16/2024 **Time:** 9:29 AM
Name of School Corporation: CULVER EDUCATIONAL FOUNDATION **Corp ID:** 50001Z
Address of School Corporation: 1300 Academy Rd 154
City: Culver **Zip:** 46511 **County Number:** 50
VIN: IGB3G3BG6D1145861 **License Number:** B668J **Bus Number:** 105
Make of Body: Chevrolet **Year:** 2013 **Make of Chassis:** Chevrolet **Year:** 2013
Bus Type: A1 **Mileage:** 57475
Inspection Status: R **Inspected By:** Travis Harrold **PE:** 8022

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.