REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	4/16/2024	**Time:**	9:29 AM
Name of School Corporation:	CULVER EDUCATIONAL FOUNDATION			**Corp ID:**	50001Z
Address of School Corporation:	1300 Academy Rd 154				
City:	Culver	**Zip:**	46511	**County Number:**	50
VIN:	IGB3G3BG6D1145861	**License Number:**	B668J	**Bus Number:**	105
Make of Body:	Chevrolet **Year:** 2013	**Make of Chassis:**	Chevrolet	**Year:**	2013
Bus Type:	A1	**Mileage:**	57475		
Inspection Status:	R	**Inspected By:**	Travis Harrold	**PE:**	8022

Violations - Rejected

Inspection Code	Description
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**